









COSHH RISK ASSESSMENT RECORD

MATERIAL SAFETY DATA SHEETS FOR ALL SUBSTANCES USED ARE LOCATED AT M W CRIPWELL HEAD OFFICE.

PRODUCT NAME	GALVAFROID	PRODUCT CODE	
MANUFACTURER	FOSROC LTD	CAS Ref .	95-63-6
Manufacturer Contact Number	01827 262222	DESCRIPTION	Cold Galvanising Paint
LOCATION(S) OF USE	Mansfield Community Hospital OPD and Holbeck wards	DATE of MSDS	
MSDS HELD	YES		
	HAZARD CLASSIFICATION (Tick as appropriate)		
	Irritant <input checked="" type="checkbox"/>	Corrosive <input type="checkbox"/>	None significant <input type="checkbox"/>
	Toxic <input type="checkbox"/>	Very Toxic <input type="checkbox"/>	Harmful (inhalation) <input checked="" type="checkbox"/>
	Flammable <input checked="" type="checkbox"/>	Explosive <input type="checkbox"/>	Dangerous to the Environment <input checked="" type="checkbox"/>
		Oxidising <input type="checkbox"/>	
	HOW IS IT USED ? (Describe the process, quantities used, maximum temperatures reached, exposure periods) Applied to galvanised steel conduit, where steel surfaces are exposed, i.e where conduit is cut.		
	ARE ANY HAZARDOUS SUBSTANCES PRODUCED BY ANY PROCESS (eg fumes from heating a substance) Avoid ignition, substance is flammable Hydrogen gas may be produced when mixed with water.		
	WHO MIGHT IT EFFECT ? (Consider not only those using it, but also visitors, those working near by etc) M W C employees and persons in the immediate vicinity		
	WHAT CONTROLS ARE CURRENTLY IN PLACE ?		
	Total enclosure of process <input type="checkbox"/>	Partial enclosure of process <input type="checkbox"/>	General workplace ventilation <input checked="" type="checkbox"/>
	Wet methods (to control dust) <input type="checkbox"/>	Respiratory Protection <input type="checkbox"/>	Eye Protection <input checked="" type="checkbox"/>
	Gloves <input checked="" type="checkbox"/>	Protective Overalls <input checked="" type="checkbox"/>	Other Please specify <input type="checkbox"/>
	GENERAL PRECAUTIONS & PERSONAL PROTECTION NEEDED (Consider warning signs, ventilation, work patterns, personal hygiene / cleanliness, protective clothing) No smoking signs to be displayed. Well ventilated area required.		

